

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

TIC 50-394 395

FEB 1 2 1980

In Reply Refer To: RII:LM 50-325/80-2 50-324/80-2

Carolina Power and Light Company
ATTN: J. A. Jones
Senior Executive Vice President and
Chief Operating Officer
411 Fayetteville Street
Raleigh, N. C. 27602

Gentlemen:

This refers to the inspection conducted by L. Modenos of this office on January 22-23, 1980, of activities authorized by NRC Operating License Nos. DPR-71 and DPR-62 for the Brunswick facility, and to the discussion of our findings held with W. H. Sutton at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were disclosed.

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

J. C. Bryant, Acting Chief

Reactor Construction and Engineering

Support Branch

Enclosure: Inspection Report Nos. 50-325/80-2 and 50-324/80-2

cc w/encl: A. C. Tollison, Jr. Plant Manager Box 458

Southport, N. C. 28461