



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

Docket No. 50-423

12 1980

Northeast Nuclear Energy Company
ATTN: Mr. W. G. Council
Vice President - Nuclear
Engineering and Operations
P. O. Box 270
Hartford, Connecticut 06101

Gentlemen:

Subject: Error in 3/8" Orifice Design (Your letter of February 25, 1980)

Thank you for your letter, referenced above, which forwarded an interim report pursuant to 10 CFR 50.55(e) regarding the subject matter.

In your final report on this matter, please address your completed or planned corrective actions to preclude repetition of this apparent failure to properly control the design process.

Your cooperation with us is appreciated.

Sincerely,

A handwritten signature in cursive script that reads "Robert T. Carlson".

Robert T. Carlson, Chief
Reactor Construction and
Engineering Support Branch

cc:

K. W. Gray, Construction Quality Assurance Lead
H. R. Nims, Director of Nuclear Projects
J. F. Opeka, Station Superintendent
J. R. Himmelwright, Licensing Safeguards Engineer

S

8004100 606