

L80-523 FILE: RR 2 (NP-33-79-114)

April 16, 1980

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Attached are three copies of Licensee Event Report 79-098 which has been revised. The revisions to the report are indicated by a "1" in the left margin of each page.

Please destroy your previous copies of this report and replace with the attached revision.

Yours truly,

1 engDor

Terry D. Murray Station Superintendent Davis-Besse Nuclear Power Station

TDM/1jk

Attachment

cc: Mr. Victor Stello, Jr., Director Office of Inspection and Enforcement Encl: 30 copies

> Mr. Norman Haller, Director Office of Management Program Analysis Encl: 3 copies

THE TOLEDO EDISON COMPANY EDISON PLAZA

300 MADISON AVENUE

TOLEDO, GHIO 43652

8004220765