

BOSTON EDISON COMPANY
GENERAL OFFICES 800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

G. CARL ANOOGNINI
SUPERINTENDENT
NUCLEAR OPERATIONS DEPARTMENT

April 17, 1980

BECo Ltr. #80-74

Mr. Thomas A. Ippolito, Chief
Operating Reactors Branch #3
Division of Operating Reactors
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

License No. DPR-35
Docket No. 50-293


Typographical Correction to Pilgrim 1
Reload 4 Licensing Submittal NEDO-24224

Dear Mr. Ippolito:

Please be advised that on page 2 of the subject document, the Doppler Coefficient value as printed is incorrect. The correct value is $-0.228/-0.217$. This is a typographical error in the data book and was discussed with the members of your staff involved in the review of this submittal. It does not affect any of the calculations.

Should there be any further questions on this subject, please do not hesitate to contact us.

Very truly yours,



JDK/gs

A001
s
110

8004230 469