

**Public Service Company of Colorado**

16805 Weld County Road 19 1/2, Platteville, Colorado 80651

May 15, 1980
Fort St. Vrain
Unit No. 1
P-80103

Mr. Karl V. Seyfrit, Director
Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

Reference: Facility Operating License
No. DPR-34


Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/80-20, Final, submitted per the requirements of Technical Specification AC 7.5.2(b)1 and AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/80-20.

Very truly yours,


Don Warembourg
Manager, Nuclear Production

DW/clb

Enclosure

cc: Director, MIPC

*Doc
5/11*