



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

TIC  
30-416  
417

PRODUCTION DEPARTMENT

January 9, 1980

09 JAN 15 11:25  
USNRC REGION  
ATLANTA OFFICE

Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, N. W., Suite 3100  
Atlanta, Georgia 30303

ATTENTION: Mr. J. P. O'Reilly, Director

Gentlemen:

SUBJECT: Grand Gulf Nuclear Station  
File 0260/0472/L-401.0/15521  
Evaluation of IE Bulletin 79-25  
AECM-80/01

NRC IE Bulletin No. 79-25 "Failures of Westinghouse BFD Relays in Safety Related Systems" expresses concern due to repeated failure of type BFD and modified BFD relays installed in ESF Systems.

We have completed our review of Class IE systems for Grand Gulf Nuclear Station Units 1 & 2 and have determined that no type BFD relays are being used by us.

Yours truly,

L. F. Dale  
Nuclear Project Manager

MRK/JDR:pa

cc: Mr. N. L. Stampley  
Mr. R. B. McGehee  
Mr. T. B. Conner

Mr. Victor Stello, Jr., Director  
Division of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission

FIGURE 2.8 - 3

MP&L QUALITY ASSURANCE REVIEW SHEET  
GGNS PROJECT MANUALS/DOCUMENTS

Part I - To be completed by the responsible Section

- Manual
- Document

Title IE Bulletin 79-25 Evaluation  
AECM-80/01

Review Request Letter No.: PMI-\_\_\_/\_\_\_ Dated: \_\_\_\_\_

Review Due Date: \_\_\_\_\_

Part II - To be completed by Reviewer(s)

Approved by: W.E. Edge for T.E. Reaves Date: 1/2/80  
Manager of Quality Assurance

Reviewer's Signature W.E. Edge Date: 1/2/80

- No comments
- Comments \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Reviewer's Signature \_\_\_\_\_ Date: \_\_\_\_\_

- No comments
- Comments \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Attach Additional Sheets If Necessary.

Return to  Administration Section

Licensing Section