

December 29, 1971

POOR ORIGINAL

**F. A. Harris, Director  
Division of Hunter Licensing**

**FOUNDATION STABILIZATION BY SPLIT-SPACED GROUPING - FLORIDA  
POWER CORPORATION (CRYSTAL RIVER UNIT 3) - DOCKET NO. 50-302**

In response to your memorandum of December 7, 1971, on above subject, an inspection was performed of Crystal River 3 to examine the performance of the foundation grouting program as proposed and accepted for issuance of the Crystal River 3 construction permit.

The inspection confirmed that the grouting program as proposed and accepted for issuance of the construction permit has been fully carried out in a satisfactory manner. There were no substantial modifications or additions to the basic procedures.

The results of this inspection will be reported in CO Inspection Report No. 50-302/71-6.

Original signed by  
R. H. Engelken

*for*  
**Lawrence B. Low, Director  
Division of Compliance**

bcc: J. G. Davis, CO:II

*50-302  
Inspection*

8002280 767

OFFICE ▶	CO	CO	CO	CO	CO
	<i>AW</i>	<i>AW for J.H.</i>	<i>RHE</i>	<i>L. J. Beratan</i>	<i>RHE</i>
SURNAME ▶	DEWhitesell:nv	JBHenderson	RHEngelken	LLBeratan	LDLow <i>for</i>
DATE ▶	12/29/71	12/29/71	12/29/71	12/29/71	12/29/71

P. A. Morris, Director  
Division of Reactor Licensing

REQUEST FOR CONFIRMATORY INFORMATION REGARDING CRYSTAL RIVER UNIT 3  
OPERATING LICENSE-FLORIDA POWER CORPORATION-DOCKET NO. 50-302

In response to your memorandum of December 7, 1971, of above subject, an inspection was performed of Crystal River 3 to examine the performance of the foundation grouting program as proposed and accepted for issuance of the Crystal River 3 construction permit.

The inspection confirmed that the grouting program as proposed and accepted for issuance of the construction permit has been fully carried out in a satisfactory manner. There were no substantial modifications or additions to the basic procedures.

The results of this inspection will be reported in CO Inspection Report No. 50-302/71-6.

L. D. Low  
Director