



**Florida
Power**
CORPORATION

June 25, 1973

Mr. S. E. Kruesi, Director
The Directorate of Regulatory Operations
U.S. Atomic Energy Commission
Washington, D.C. 20545

Subject: Crystal River Plant - Unit #3
Docket No. 50-302

Dear Mr. Kruesi:

On June 20, 1973, Florida Power Corporation advised the DRO Region II office of our possible involvement in a situation which could be considered reportable under Federal Regulation 10 CFR50.55(e). This situation involved incomplete documentation in the weld filler material records for reactor vessels, closure heads, and pressurizers fabricated by the Babcock & Wilcox Company.

A report on the investigation of these records was submitted to the Atomic Energy Commission by Babcock & Wilcox. A copy of the report, BAW-1403, identifying our involvement will be maintained at the Crystal River Unit #3 site.

Please advise if further information on this matter is required.

Very truly yours,

FLORIDA POWER CORPORATION

Richard E. Raymond
Senior Vice President

RER/iw

cc: Mr. Norman Moseley
Director, Region II

8008191083