

## UNITED STATES ATOMIC ENERGY COMMISSION WASHINGTON, D.C. 20545

APR 2 6 1973

G. S. Spencer, Chief, Reactor Construction and Operations Branch, RO:V

RANCHO SECO - DOCKET NO. 50-312 - MINOR IMPERFECTIONS IN PIPE WELDS

The enclosed letter from DeYoung to SMUD, dated April 25, 1973, concerning the acceptance of the licensee's evaluation of subject, is forwarded for your information. If this is still being carried as an outstanding item, the enclosure provides the basis for closing this problem.

RO has no further questions concerning this matter.

J. B. Henderson, Chief Construction Branch, RO