



LONG ISLAND LIGHTING COMPANY

SHOREHAM NUCLEAR POWER STATION

P.O. BOX 618, NORTH COUNTRY ROAD • WADING RIVER, N.Y. 11792

February 19, 1980

SNRC-462

Mr. Boyce H. Grier
Office of Inspection and Enforcement, Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

LONG ISLAND LIGHTING COMPANY
SHOREHAM NUCLEAR POWER STATION - UNIT 1
DOCKET NO. 50-222

Dear Mr. Grier:

NRC Inspection and Enforcement Bulletin 79-28 addresses defects in certain NAMCO model EA180 series switches, as reported by NAMCO under the requirements of 10CFR Part 21.

We have reviewed the application of such switches at Shoreham and have determined that affected switches were procured as a result of Bulletin 78-04. These switches shall be returned to NAMCO for rework, as stated in the attachment to Bulletin 79-28, and documentation will be required to verify completion of the modifications.

Very truly yours,

J. P. Novarro
Project Manager
Shoreham Nuclear Power Station

MAG:jb

cc: Mr. Victor Stello, Director
NRC Office of Inspection and Enforcement
Div. of Reactor Operations Inspection
Washington, D.C. 20555

cc: Mr. J. Higgins
Site NRC Trailer