



HELPING BUILD ARKANSAS

IE FILE COPY

ARKANSAS POWER & LIGHT COMPANY

P.O. BOX 551 LITTLE ROCK, ARKANSAS 72203 • (501) 371-4000

September 8, 1977



1-097-6

Mr. E. Morris Howard, Director
Office of Inspection & Enforcement
Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One-Unit 1
Docket No. 50-313
License No. DPR-51
Reportable Occurrence Report No. 50-313/77-18
(File: 0520)

Gentlemen:

In accordance with Technical Specification 6.12.3.1, we have attached the subject report concerning the inoperability of the Hydrogen Purge System due to its inability to achieve an adequate flow rate during surveillance testing.

Very truly yours,

Donald A. Rueter
Manager, Licensing

DAR:REI:tw

Attachment

cc: Mr. W. D. MacDonald, Director
Office of Management Information
and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

cc: Dr. E. Volgenau, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8004110 702

