



435 Sixth Avenue  
Pittsburgh, Pa.  
15219

(412) 456-6000

April 14, 1980

Director of Nuclear Reactor Regulation  
United States Nuclear Regulatory Commission  
Attn: D. G. Eisenhut, Acting Director  
Division of Operating Reactors  
Washington, DC 20555

Reference: Beaver Valley Power Station, Unit No. 1  
Docket No. 50-334  
Quality Assurance Requirements Regarding Diesel Generator Fuel Oil

Gentlemen:

We have reviewed your January 7, 1980, letter regarding QA requirements for emergency diesel generator fuel oil. We presently do not include diesel generator fuel oil in our Quality Assurance Program. However, we have reviewed Regulatory Guide 1.137, "Fuel Oil Systems for Standby Diesel Generators," and we will implement those sections which can be accomplished without modification to installed station facilities prior to station startup following the current modification and refueling outage. Sections which can be implemented include Sections C.2.a, C.2.b, C.2.c and C.2.f.

Compliance with the remainder of the Regulatory Guide sections will require some modifications to station equipment, and therefore, implementation of these requirements may be delayed until the third refueling shutdown. However, those modifications which can be accomplished sooner than the third refueling shutdown will be implemented when they are completed.

Should you have any questions or require additional information, please contact this office.

Very truly yours,

C. N. Dunn  
Vice President, Operations

*AOZ  
5/10*

8004220594