



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

April 15, 1980

2-040-07

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Licensee Event Report No.  
80-017/03L-0  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One-Unit 2 Technical Specification 6.9.1.9.b, attached is the subject report concerning a Steam Generator pressure indicator failure.

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

DCT:MAS:sh

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Norman M. Haller, Director  
Office of Management and Program  
Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555