

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

April 14, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303


Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT UNIT A1 - REPORTABLE DEFICIENCY -
CRACKS IN RPV SHIELD WALL (NCR HNP-A-091)

Initial notification of the subject deficiency was made to R. W. Wright, NRC-OIE, Region II on March 14, 1980. In compliance with paragraph 50.55(e) of 10 CFR Part 50, enclosed is the first interim report of the subject deficiency. TVA anticipates transmitting the final report on or before July 7, 1980. If you have any questions concerning this subject, please call Jim Domer at FTS 854-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

BO19
SE
1/1