



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

11/11 31

PRODUCTION DEPARTMENT

March 31, 1980

Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta St., N.W., Suite 3100  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Director

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station  
Units 1 and 2  
Dockets Nos. 50-416 and 50-417  
File 0272/15526/L-860.0  
PRD-80/03, Interim Report,  
Damaged Instrumentation Cables  
Under Reactor Pressure Vessel  
AECM-80/60

On February 28, 1980, Mississippi Power & Light Company notified Mr. M. J. Gouge of your office of a deficiency concerning damaged instrumentation cables under the Reactor Pressure Vessel (RPV). Mr. Gouge was notified at that time of our determination that this matter was not reportable within the meaning of 10CFR50.55(e). This notification was made for information purposes only. On March 6, 1980, Mr. Gouge informed Mississippi Power & Light Company that this deficiency should be considered and processed as a reportable condition.

Our interim report on this deficiency is attached. Our investigation and corrective action plan is presently incomplete. We expect to provide a final report on this matter by June 9, 1980.

Yours truly,

For L. F. Dale  
Nuclear Project Manager

JGC/JDR:ts  
Attachment

cc: Mr. N. L. Stampley  
Mr. R. B. McGehee

Mr. Victor Stello, Jr., Director  
Division of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

B019  
SE  
1/1

Member Middle South Utilities System

8004280

517