

Tex



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

April 21, 1980

D L ASWELL
Vice President-Power Production

LPL 13617
Q-3-A35.02.01
Q-3-A35.07.13

Mr K V Seyfrit, Director, Region IV
U S Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3
Final Report of Significant
Construction Deficiency No 13
"Reactor Containment Building Dome Concrete"

Reference: 1) LP&L Letter LPL 11994 to NRC dated 9-14-79 - Interim Report;
2) LP&L Letter LPL 12376 to NRC dated 11-28-79 - Supplement No 1 to
Interim Report;
3) LP&L Letter LPL 12968 to NRC dated 1-30-80 - Status Report - SCD
No 13

Dear Mr Seyfrit:

In accordance with the requirements of 10CFR50.55(e), we are hereby providing two (2) copies of the Final Report of Significant Construction Deficiency No 13, "Reactor Containment Building Dome Concrete".

All corrective action repairs for this deficiency have been completed and verification testing has been accomplished. If we can be of further assistance in this matter, please advise.

Very truly yours,

D L Aswell

DLA/LLB b1

Enclosures

cc: 1) Director
Office of Inspection and Enforcement
U S Nuclear Regulatory Commission
Washington, D C 20555
(with 15 copies of report)

2) Director
Office of Management
Information and Program Control
U S Nuclear Regulatory Commission
Washington, D C 20555
(with 1 copy of report)

*BO19
SE
1/1*

8004280596