

TENNESSEE VALLEY AUTHORITY

C. B. ANNOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

April 24, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 2 - SAFETY-RELATED CABLE INSIDE CONTAINMENT
NOT QUALIFIED - NCR SQN QEB 8002 - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
M. J. Gouge on March 25, 1980, in accordance with 10 CFR 50.55(e).
Enclosed is our first interim report. We expect to submit our next
report by June 27, 1980.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Boia
5/11