



8 005 060233

ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

May 2, 1980

1-050-01

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

SUBJECT: ARKANSAS NUCLEAR ONE - UNIT 1  
Docket No. 50-313  
License No. DPR-51  
Licensee Event Report No. 80-012/03L-0  
(File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 1 Technical Specification 6.12.3.2.b, the attached is the subject report concerning the emergency feedwater supply valve, CV2667, that failed to open fully on demand; and, the next day, failed to open along with the emergency feedwater supply valve, CV2617.

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

DCT:GAC:lp

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555

Mr. Norman M. Haller, Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, D.C. 20555