

**Florida  
Power**  
CORPORATION

April 30, 1980

File: 3-0.3.a.4

U. S. Nuclear Regulatory Commission  
Director of Reactor Construction Inspection, O.I.E.  
Washington, DC 20555

Subject: Crystal River Unit #3  
Docket No. 50-302  
Operating License No. DPR-72  
IE Bulletin 80-09  
HYDRAMOTOR ACTUATOR DEFICIENCIES

Gentlemen:

In response to your letter to us, dated April 17, 1980, transmitting the subject bulletin, we have determined that there are no AH-90 nor NH-90 series Hydramotor Actuators manufactured by ITT General Controls used in any safety-related system or component at Crystal River Unit 3 Nuclear Plant. Therefore no further information is required in response to the subject bulletin.

Please contact this office if you require any additional discussion concerning our response.

Very truly yours,

FLORIDA POWER CORPORATION

*Patsy Y. Baynard*

Patsy Y. Baynard  
Manager  
Nuclear Support Services

EETheW04(D70)

cc: Mr. J. P. O'Reilly  
Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Suite 3100  
101 Marietta Street  
Atlanta, GA 30303

*A001  
.5  
1/10*