

TELECOPY MESSAGE

Telephone Number _____

Date/Time: 3/8/80 / 1980

Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

From: Pilgrim Nuclear Power Station
RFD #1 Rocky Hill Road
Plymouth, MA 02360

Subject: PROMPT REPORTABLE OCCURRENCE
Docket Number 50-293; License DPR-35
Assigned LER Number 80-004/01X-0

Event Description: Two irradiated fuel assemblies were re-located in the spent fuel pool on 3-8-80 with the diesel generators inoperable and secondary containment not intact. This is in violation of Technical Specifications 3.7.3.1 and 3.7.C.1.c.

Cause and Corrective Action: This event was caused by a misunderstanding of the diesel generator operability status and core drilling for modifications. Fuel movements were terminated and event will be reviewed by responsible individuals.

Operability Status:
Routine Startup _____
Routine Shutdown _____
Steady State _____
Load Changing _____

0 Thermal MW
g) Shutdown _____
h) Refueling _____
i) Other _____
j) Not Applicable _____

Written follow-up report will be sent within two weeks.

Person notified Operations Duty Officer

Prepared by Mr. C. J. Machis

(2) copies to:
Director
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

POOR ORIGINAL