

716 Edney Building

May 1, 1980

Mr. James P. O'Reilly, Director
 U.S. Nuclear Regulatory Commission
 Office of Inspection and Enforcement
 Region II
 101 Marietta Street, Suite 2150
 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET
 NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE
 REPORT SQRO-50-327/6023

The enclosed report provides details concerning diesel generator 2A-A
 feeder air circuit breaker which failed to close with diesel generator 1B-B
 being tagged out for maintenance. This report is submitted in accordance
 with Sequoyah unit 1 Technical Specification 5.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun
 Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
 Office of Management Information and Program Control
 U.S. Nuclear Regulatory Commission
 Washington, DC 20555

Director (40)
 Office of Inspection and Enforcement
 U.S. Nuclear Regulatory Commission
 Washington, DC 20555

Mr. Bill Lavallee
 Nuclear Safety Analysis Center
 Palo Alto, California 94305

Mr. W. T. Cobble, NRC Inspector, Sequoyah

POOR ORIGINAL

A002
 S
 1/1