3 005080 463

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE BOX 764

COLUMBIA, SOUTH CAROLINA 29218

E.H. CREWS, JR. VICE-PRESIDENT AND GROUP ENTEUTIVE ENGINEERING AND CONSTRUCTION

April 22, 1980

Mr. James ?. O'Reilly, Director U. S. Nuclear Regulatory Commission Region II. Suite 3100 101 Marietta Street, N. W. Atlanta, Georgia 30303

> Virgil C. Summer Nuclear Station Subject: Reportable Substantial Safety Hazard Service Water Booster Pump Motor Failure

Nuclear ineering File 3.1051

Dear Mr. O'Reilly:

On March 28, 1980 South Carolina Electric & Gas Company reported to the NRC that we were reviewing the failure of one of our service water booster pumps as a potential substantial safety hazard as defined by 10CFR21. We have determined that the item is reportable, and we are reporting it as a significant deficiency under 10CFR50.55(e). Details are presented on the attached sheets.

This is considered the final report on this item. If you require further information, place contact us.

Very truly yours,

Crews, Jr.

JAW: EHC: rh

cc: H. T. Babb

E. H. Crews, Jr.

O. S. Bradham

D. A. Nauman

H. Radin

J. Skolds

V. C. Summer

NPCF/Dixon

File