



8005080518

5

ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

May 5, 1980

2-050-03

Mr. K. V. Seyfrit, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Licensee Event Report No. 80-018/03L-0
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One Unit 2 Technical Specification 6.9.1.9b., attached is the subject report concerning the Emergency Feed-water Pumps (EFP) that lost feed pump suction following a transient loss of offsite power.

Very truly yours,

David C. Trimble
Manager, Licensing

DCT:GAC:ms

Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555