

P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 666-6911

May 1, 1980 MP-2-4379

Mr. Boyce H. Grier Director, Region I Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Reference:

Facility Operating License No. DPR-65

Docket No. 50-336

Reportable Occurrence RO-50-336/80-16/3L-0

Dear Mr. Grier:

This letter forwards Licensee Event Report 80-16/3L-0 required to be submitted within thirty days pursuant to Millstone Unit 2 Appendix A Technical Specifications, Section 6.9.1.9.a, reactor protection system instrument settings which are found to be less conservative than those established by the technical specifications, but which do not prevent fulfillment of the functional requirements. An additional three copies of the report are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

for

John F. Opeka Station Superintendent

Millstone Nuclear Power Station

JFO/RWB:11s

Attachment:

LER 80-16/3L-0

cc: Director, Office of Inspection and Enforcement, Washington,

D.C. (30)

Director, Office of Management Information and Program Control,

Washington, D.C. (3)