

**NSP**

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

May 9, 1980

Mr J G Keppler  
Office of Inspection & Enforcement  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr Keppler:


PRAIRIE ISLAND NUCLEAR GENERATING PLANT  
Docket No. 50-306 License No. DPR-60

22 TD AFW Pump Overspeed Trip Valve Trip

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reportable in accordance with Technical Specification 6.7.B.2.(b) in that this valve trip led to operation in a degraded mode permitted by a limiting condition for operation, Specification 3.4.B.

Yours very truly,

  
L O Mayer, PE  
Manager of Nuclear Support Services

LOM/JAG/jh

cc: Director, IE, USNRC (30)  
Director, MIPC, USNRC (3)  
MPCA  
Attn: J W Ferman