

80 051 30571 5



FLORIDA POWER & LIGHT COMPANY

May 7, 1980

PRN-LI-80-184

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-80-06
TURKEY POINT UNIT 4
DATE OF OCCURRENCE: APRIL 7, 1980

TECHNICAL SPECIFICATION 4.10.1
AUXILIARY FEEDWATER SYSTEM

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9.2 to provide 30 day notification of the subject occurrence.

Very truly yours,

A. D. Schmidt
Vice President
Power Resources

MAS/pa

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and
Program Control (3)
Harold F. Reis, Esquire
File: 933.1 TP