

PANHANDLE EASTERN PIPE LINE COMPANY

SUITE 360 • 10890 BENSON  
OVERLAND PARK, KANSAS 66212  
(913) 341-1400

December 9, 1980

MAILING ADDRESS:  
P. O. BOX 12330  
OVERLAND PARK, KANS. 66212

U. S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
ARLINGTON, Texas 76012

ATTENTION: Karl V. Seyfrit, Director


RE: IE Circular No. 79-16, dated  
August 16, 1979 and IE Bulletin  
No. 80-22, dated September 12,  
1980

Dear Sir:

The following is the action taken by Panhandle Eastern to assure the safe operation of radiography equipment, and as requested in the above referenced correspondence:

1. Panhandle Eastern Pipe Line Company has determined there are no AI Model 200-520-008 or other assemblies in our inventory.
2. Not applicable, since we do not have any of this type equipment.
3. This matter was reviewed with all Panhandle radiographers during the month of September, 1979, and during the Annual Radiographers Training, the week of October 20, 1980.
4. Not applicable, since we do not have any of this type equipment.
5. Discussion with the radiographers took place during the training referenced in #3 above.

Yours truly,

  
Kenneth F. L. Dohrman  
Radiation Safety Officer

cc: Director, Division of Fuel Facility  
and Materials Safety Inspection,  
Office of Inspection and Enforcement,  
U. S. Nuclear Regulatory Commission,  
Washington, D. C. 20555

8102170 599