

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II!
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

MAR 3 1980

Docket No. 50-266 Docket No. 50-301

Wisconsin Electric Power Company ATTN: Mr. Sol Burnstein Executive Vice President Power Plants 231 West Michigan Avenue Milwaukee, WI 53201

Gentlemen:

Thank you for your letter dated February 11, 1980, informing us of the steps you have taken, or plan to take, to correct the noncompliance identified in our letter dated January 11, 1980. We will examine your corrective action during a subsequent inspection.

Based on a review of our records, we have determined that the item of noncompliance in Appendix A to our January 11, 1980 letter (Inspection Report No. 50-266/79-18 and No. 50-301/79-19) should have been classified as a deficiency rather than an infraction. Hence, we are enclosing a revised Appendix A to our January 11, 1980 letter for your records. We informed Mr. J. Greenwood of your staff of this change by telephone on February 5, 1980.

Your cooperation with us is appreciated.

Sincerely,

A. B. Davis, Chief

Fuel Facility and Materials

Safety Branch

Enclosure: As stated

cc w/encl: Mr. G. A. Reed, Plant Manager C. W. Fay, Director

Nuclear Power Department

cc w/encl & w/ltr dtd 2/11/80: Central Files Reproduction Unit NRC 20b PDR Local PDR NSIC

TIC
Sandra A. Bast, Lakeshore
Citizens for Safe Energy
Mr. John J. Duffy, Chief
Boiler Inspector, Dept. of
Industry, Labor and Human Relations