

ARKANSAS POWER & LIGHT COMPANY POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

June 13, 1980

1-060-09

Mr. K. V. Seyfrit, Director Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Subject: Arkansas Nuclear One-Unit 1

Docket No. 50-313 License No. DPR-51

Licensee Event Report No.

80-017/03L-3 (File: 0520)

Gentlemen:

In accordance with Arkansas Nuclear One-Unit 1 Technical Specification 6.12.3.2(b) attached is the subject report concerning the failure of a bypass damper.

Very truly yours,

David C. Trimble Manager, Licensing

DCT:GAC:sh Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Norman M. Haller, Director Office of Management and Program Analysis U. S. Nculear Regulatory Commission Washington, D. C. 20555