



UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION II - SUITE 818
230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30303

TELEPHONE: (404) 526-4503

March 13, 1972

J. G. Keppler, Chief, Reactor Testing and Operations Branch (2)
Division of Compliance, Headquarters

CO INQUIRY REPORT NO. 50-269/72-3
DUKE POWER COMPANY (OCONEE 1), LICENSE NO. CPPR-33, DOCKET N). 50-269
ACCIDENTAL TRIP OF ECCS SYSTEMS

The subject inquiry report is forwarded for your information. Consideration is being given to asking Duke Power Company for a formal report of this occurrence; however, at this time, a decision has not been reached.

We will review this occurrence in depth during the next inspection which is currently planned for the week beginning March 27, 1972.

N. C. Moseley
Senior Reactor Inspector

CO:II:NCM

Enclosure:
CO Inquiry Rpt. No.
50-269/72-3 (Murphy)

cc w/encl:
E. G. Case, DRS (3)
R. S. Boyd, DRL (2)
R. C. DeYoung, DRL (2)
D. J. Skovholt, DRL (3)
H. R. Denton, DRL (2)
L. Kornblith, Jr., CO
R. H. Engelken, CO
J. B. Henderson, CO
J. P. O'Reilly, CO:I
B. H. Grier, CO:III
J. W. Flora, CO:IV
R. W. Smith, CO:V
CO Files
DR Central Files



7911210 742

5