NAMCO CONTROLS

7567 TYLER BOULEVARD . MENTOR, OHIO 44060 . (216) 946-9900

May 29, 1980

U.S. Nuclear Regulatory Commission Region 1V 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

Attention: Uldis Potapovs, Chief Vendor Inspection Branch

1 1980

Subject: Docket No. 99900378/80-01 QA Program Inspection February 11-14, 1980

## Gentlemen:

This letter is in response to your letter of April 29, 1980, and Notice of Deviation which indicated that Namco Controls' Quality Assurance Program was deficient in the area of documented procedures.

Namco Controls acknowledges that the Documentations of Procedures referenced in your notice are incomplete in the following areas:

- 1. Engineering Changes & Design Review
- 2. Material Review Board
- 3. Calibration Procedures

We are in the process of documenting the procedures in the above areas, and we expect to have these completed by October 1, 1980.

With respect to the items listed below, we expect to have complete documentation by February 1, 1981:

- 1. Internal Audits
- 2. Procurement Controls
- 3. Material Storage

Upon completion of these written procedures, we understand that Namco Controls will be in full compliance with the requirements of 10CFR50.

Thank you for your interest in our behalf.

Very truly yours,

N. E. Swanson President NAMCO CONTROLS

NES/kg

8006240146