PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET
P.O. BOX 8699
PHILADELPHIA, PA. 19101

(215) 841-4502

JOHN S. KEMPER
VICE-PRESIDENT
ENGINEERING AND RESEARCH

Mr. Boyce Griar, Director Office of Inspection and Enforcement Commission United States Nuclear Regulatory Commission 631 Park Avanua Eing of Prussia, PA 19406

Subjecti

Significant Deficiency Report No. 11 42V Switchgear Circuit Breaker Auxiliary Switch Crank Assembly Defect

Rafarance:

Telecon of May 22, 1930 H. R. Walters (PECO) to R. McGaughy (NRC)

7114:

QUAL 2-10-2 (3DR #11)

Dear Mr. Grier:

Attached is our final report on the above subject deficiency which was reported to the USNRC per the referenced talacon in accordance with 10CFR50.55(e).

If there are any questions on the matter we would be pleased to discuss them with you.

Sincerely,

RJL/gra Attachment

Copy to: Director of Inspection and Enforcement United States Nuclear Regulatory Commission Washington, D.C. 20555

> 1/1 A003

POOR ORIGINAL