

THE CHURCH OF
JESUS CHRIST
OF LATTER-DAY SAINTS

RUPERT ID FM GROUP
1814 H Street
Rupert, Idaho 83350-1054
Phone 1-208-434-1421
Toll free: 1-866-434-1421
Facsimile: 1-208-434-1423

October 15, 2019

U.S. Nuclear Regulatory Commission
Director of Nuclear Material Safety & Safeguards
ATTN: GLTS
Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on 10-21-19 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2022. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Rhonda Shaw at 208-434-1421.

Sincerely,



Rhonda Shaw
Rupert ID AA

Encl.

SERIAL NUMBER SPREADSHEET

Company Name	Rupert ID FM Group	Date	09/30/19
Address 1	1814 H Street	Isolite RMA #	15162
Address 2		EWS Order #	N/A
Address 3		MTS Order #s	FMACQ-280519
City/State	Rupert, ID	Contact Name	Rhonda Shaw
Zip/Post Code	83350	Contact Phone	208-434-1421
Country	United States	Contact FAX	N/A
		Contact E-mail	

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	SRB Tech	B100	674927	4	02	20 "CI"
2	SRB Tech	B100	674933	4	02	20 "CI"
3	SRB Tech	B100	674928	4	02	20 "CI"
4	SRB Tech	B100	674929	4	02	20 "CI"
5	SRB Tech	B100	C042821	3	08	20 "CI"
6	SRB Tech	B100	C042820	3	08	20 "CI"
7	Isolite Corp	2040	A58344	10	15	11.5 "CI"
8	Isolite Corp	SLX-60	412802	6	07	11.5 "CI"
9	Isolite Corp	SLX-60	412801	6	07	11.5 "CI"
10	SRB Tech	B100	C084408	3	11	21.6 "CI"
11	SRB Tech	B100	C084409	3	11	21.6 "CI"
12	Omniglo	700-3020	8898	7	92	20 "CI"
13	Omniglo	700-3020	8899	7	92	20 "CI"
14	Isolite Corp	SLX-60	13-15757	1	14	464 "TBq"
15	Isolite Corp	SLX-60	13-15758	1	14	464 "TBq"

The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	Rupert ID FM Group	Date	09/30/19
Address 1	1814 H Street	Isolite RMA #	15162
Address 2		EWS Order #	N/A
Address 3		MTS Order #s	FMACQ-280519
City/State	Rupert, ID	Contact Name	Rhonda Shaw
Zip/Post Code	83350	Contact Phone	208-434-1421
Country	United States	Contact FAX	N/A
		Contact E-mail	

16

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	Isolite Corp	SLX-60	13-15755	1	14	464 TBq
2						
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.