

FILE



June 23, 1978

L78-277
FILE: RR 2 (NP-33-78-72)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

TOLEDO EDISON
Nuclear Services
JUN 26 1978

Dear Mr. Keppler:

Reportable Occurrence 78-060
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: May 28, 1978

Enclosed find three copies of Licensee Event Report 78-060 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/JRL/ljk

Enclosures

cc: Dr. Ernst Volgenau, Director
Office of Inspection and Enforcement
Encl: 30 copies LER 78-060

Mr. William G. McDonald, Director
Office of Management Information
and Program Control
Encl: 3 copies LER 78-060

JUN 29 1978

8001270093

A002
5/11