




HELPING BUILD ARKANSAS

ARKANSAS POWER & LIGHT COMPANY

9TH & LOUISIANA STREETS • LITTLE ROCK, ARKANSAS 72203 • (501) 372-4311

January 30, 1975



Mr. E. G. Case, Acting Director
Office of Nuclear Reactor Regulations
United States Nuclear Regulatory Commission
Washington, D. C. 20555

Subject: Arkansas Power & Light Company
Arkansas Nuclear One-Unit 1
Docket No. 50-313
License No. DPR-51
Abnormal Occurrence
Report No. 50-313/75-1

Dear Mr. Case:

On January 21, 1975, we reported an abnormal occurrence involving Service Water Inlet Valve CV-3813 and Outlet Valve CV-3814 at Arkansas Nuclear One-Unit 1 to Mr. Norman C. Moseley, Director, Office of Inspection & Enforcement, Region II.

Attached is our report on this occurrence as required by Technical Specifications 6.12.3.1

Very truly yours,

J. D. Phillips
Senior Vice President

JDP:tw

Attachment

cc: Mr. Norman C. Moseley, Director
Office of Inspection & Enforcement
Region II
United States Nuclear Regulatory Commission
230 Peachtree St., N.W., Suite 818
Atlanta, Georgia 30303

8004110-653

