

HELPING BUILD ARKANSAS


ARKANSAS POWER & LIGHT COMPANY

PO. BOX 551 LITTLE ROCK, ARKANSAS 72203 - (501, 371 - 4000

February 2, 1977

1-027-1

Mr. E. Morris Howard, Director Office of Inspection & Enforcement Region IV U. S. Nuclear Regulatory Commission 611 Ryan Plaza Drive, Suite 1900 Arlington, Texas 76011



Docket No. 50-313 License No. DPR-51

Reportable Occurrence Report

No. 50-313/77-1 (File: 0520)

Gentlemen:

In accordance with Technical Specification 6.12.3.2, we have attached the subject report concerning removing of the SLBIC System from service for less than 24 hours due to frozen sensing lines.

Very truly yours,

Donald A. Rueter Manager, Licensing

DAR: tw

Attachment

cc: Mr. W. D. MacDonald, Director
Office of Management Information
and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dr. E. Volgenau, Director Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555 THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

8004120 PIO

