



HELPING BUILD ARKANSAS

ARKANSAS POWER & LIGHT COMPANY

P.O. BOX 551 LITTLE ROCK, ARKANSAS 72203 • (501) 371-4000

November 1, 1976

1-116-1

Mr. E. Morris Howard, Director
Office of Inspection & Enforcement
Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



Subject: Arkansas Power & Light Company
Arkansas Nuclear One-Unit 1
Docket No. 50-313
License No. DPR-51
Reportable Occurrence Report
Nos. 50-313/76-29 and 50-313/76-30
(File: 0520)

Gentlemen:

On October 3, 1976, two incidents delineated in the subject reports occurred involving 1) a leak in Primary Makeup Pump P36C suction relief line, and 2) Primary Makeup Pump P36B being stopped due to over-current alarm followed by loss of discharge pressure, respectively. Investigations of the latter revealed damage to the pump. Attached find these reports in accordance with Technical Specification 6.12.3.2.

Very truly yours,

Donald A. Rueter
Manager, Licensing

DAR:RMC:tw

cc: Dr. E. Volgenau, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

11253

Mr. W. D. MacDonald, Director
Office of Management Information
and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

80041406815

