

APPENDIX A

NOTICE OF VIOLATION

Manchester Memorial Hospital
Manchester, Connecticut 06040
License No. SNM-1751

Docket No. 70-2651

Based on the results of an NRC inspection conducted on February 7, 1980, it appears that one of your activities was not conducted in full compliance with the conditions of your NRC license as indicated below:

Condition 15 of your license requires that you continue patient followup during the life of the patient.

Contrary to this requirement, as of February 7, 1980, you failed to continue followup on a patient in whom a pacemaker was implanted during July, 1977. Specifically, you did not receive reports or otherwise verify that a physician outside your hospital did the followup.

This item is a deficiency.