TENNESSEE VALLEY AUTHORITY

CHAJJANOGA TENNESSEE 37401 II

July 11, 1980

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. J'Reilly:

YELLOW CREEK NUCLEAR PLANT UNIT 1 - PLACEMENT OF EARTHFILL IN ERCW SPRAY POND - NCR YC-077 - REVISED FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector M. Thomas on June 23, 1980, in accordance with 10 CFR 50.55(e). A final report was submitted on July 10, 1980. Enclosed is our revised final report.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

305

7150 659

An Equal Opportunity Employer