



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

*Jea*

JUN 30 1980

Docket Nos. 50-369  
and 50-370

MEMORANDUM FOR: Those on Attached List

FROM: R. A. Birkel, Licensing Project Manager  
Licensing Branch #1  
Division of Licensing

SUBJECT: TMI REVIEW ITEM SCHEDULE  
(McGUIRE NUCLEAR STATION, UNITS 1 & 2)

By memorandum dated June 13, 1980, we forwarded a table listing McGuire TMI review items and requested both a review of the table and a firm SSER input date. As a result of the staff response to our request, we have scheduled the review of the TMI items and have designated principal branch review responsibilities. The final schedule is shown on the enclosure.

Your continued cooperation in completing the McGuire review is appreciated.

*Ralph A. Birkel*

R. A. Birkel, Licensing Project Manager  
Licensing Branch #1  
Division of Licensing

Enclosure:  
McGuire Review - TMI Items

cc: R. Tedesco  
B. J. Youngblood  
R. Bosnak  
R. Satterfield  
F. Rosa  
W. Butler  
O. Parr  
W. Houston  
W. Gammill  
L. Phillips  
P. Collins  
D. Vassallo  
D. Ziemann  
F. Pagano  
Murphy

8007160 486

Attached List

- 2 -

JUN 30 1980

Memorandum for:

J. Tsao  
P. Stevens  
K. Giardina/A. Speed  
M. Fields  
W. LeFave  
J. Read  
R. Serbu  
J. Boegli  
G. Mazetis  
T. Huahn  
J. McMillen  
L. Crocker/C. Heit  
B. Clayton  
R. Ramirez  
E. McPeek

June 27, 1980

McGUIRE REVIEW SCHEDULE

IMI ITEMS

<u>BRANCH</u>	<u>PRINCIPAL REVIEW RESPONSIBILITY</u>	<u>SSER INPUT</u>	<u>ITFM</u>
Mech. Eng. Branch	Frank Cherney	07/15/80	II.D.1 - RCS Relief & Safety Valve Testing Requirements
Inst. & Control Sys. Branch	R. Stevens	06/01/80	II.F.1 - I. & C. Additional Accident Monitoring Instrumentation II.D.3 - RCS Relief & Safety Valve Position Indication II.E.1.2 - AFS Automatic Initiation & Flow Indication
Power Systems Branch	R. Giardina/ A. Saeed	07/11/80	II.G.1 - Electric Power - Supplies for Pressurizer Relief Valve, Block Valves, & Level Indications II.E.3.1 - Reliability of Power Supplies for natural circulation
Containment Systems Branch	M. Fields	07/15/80	II.E.4.2 - Containment Design - Isolation Dependability II.E.4.1 - Containment Design - Dedicated Penetrations
Auxiliary Systems Branch	W. LeFave	08/01/80	II.E.1.1 - Auxiliary Feedwater System Evaluation
Accident Evaluation Branch	J. Read	08/01/80	III.D.3.4 - Worker Radiation Protection Improvement - Control Room Habitability
Radiological Assessment Branch	R. Serbu	07/18/80	II.B.2 - Plant Shielding - Post Accident III.D.3.3 - Worker Radiation Protection Operation Improvement Inplant Radiation Monitoring
Effluent Treatment System Br.	J. Boegli	08/01/80	III.D.1.1 - Primary Coolant Sources Outside the Containment Structure II.B.3 - Post-Accident Sampling
Reactor Systems Branch	G. Mazetis	08/01/80	II.B.1 - Reactor Coolant System Vents II.K.1 - Measures to mitigate LOCA's - IE Bulletins II.K.3 - Measures to mitigate LOCA's - Final Recommendation of B&O Task Force
Core Performance Branch	T. Huang	" "	II.F.2 - Identification of & Recovery from Conditions Leading to Inadequate Core Cooling

<u>BRANCH</u>	<u>PRINCIPAL REVIEW RESPONSIBILITY</u>	<u>SSER INPUT</u>	<u>ITEM</u>
Operator Licensing Branch	J. McMillen	08/01/80	I.A.3.1 - Revise Scope & Criteria for Licensing Exam II.B.4 - Training for mitigating core damage
Licensee Qualification Branch	L. Crocker/C. Heit	08/01/80	I.A.1.1 - Shift Technical Advisor I.A.1.2 - Shift Technical Administrative Duties I.A.1.3 - Shift Manning I.B.1.2 - Evaluation of Organization & Management I.C.2 - Shift & Relief Turnover Procedures I.C.3 - Shift Supervisor Responsibilities I.C.4 - Control Room Access I.C.5 - Procedures for Feedback of Operating Experience
Procedures & Test Review Br.	B. Clayton	09/08/80 09/08/80 09/08/80 08/01/80	I.C.1 - Short-Term Accident Analysis and Procedures Revision I.C.7 - NSSS Vendor Review of Procedures I.C.8 - Pilot Monitoring of Selected Procedures I.G.1 - Training Requirements
Human Factors Engineering Branch	R. Ramirez	07/15	I.D.1 - Control Room Design Review
Emergency Preparedness Licensing Branch	E. McPeck	08/01/80	III.A.1.1 - Upgrade Emergency Preparedness III.A.1.2 - Upgrade Licensee Emergency Support Facility