



June 27, 1980

Mr. James G. Keppler
Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station

Docket No. 50-304/DPR-48

Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-304/80-22 for Zion Generating Station. This occurrence was reported to Region III, Directorate of Regulatory Operations by telephone on 6/19/80 and by telegram/mailgram on 6/19/80.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.a, which states that operation of the unit subject to a limiting condition which is less conservative than the least conservative aspect of the limiting condition requires a 14-day written report.

Very truly yours,

N. E. Wandke Superintendent Zion Station

Enclosure: Reportable Occurrence Report No. 50-304/80-22

JUL 9 '980'

A007