## REACTIVITY CONTROL SYSTEMS

## CONTROL ROD INSERTION LIMITS

# LIMITING CONDITION FOR OPERATION

3.1.3.5 The control banks shall be limited in physical insertion as shown in Figures 3.1-1 and 3.1-2.

APPLICABILITY: MODES 1\* and 2\*#.

#### ACTION:

With the control banks inserted beyond the above insertion limits, except for surveillance testing pursuant to Specification 4.1.3.1.2, either:

- a. Restore the control banks to within the limits within two hours, or
- b. Reduce THERMAL POWER within two hours to less than or equal to that fraction of RATED THERMAL POWER which is allowed by the group position using the above figures, or
- c. Be in HOT STANDBY within 6 hours.

### SURVEILLANCE REQUIREMENTS

4.1.3.5 The position of each control bank shall be determined to be within the insertion limits at least once per 12 hours except during time intervals when the Rod Insertion Limit Monitor is imperable, then verify the individual rod positions at least once per 4 hours.

\*See Special Test Exceptions 3.10.2 and 3.10.4. #With  $K_{\mbox{eff}} \geq 1.0$ .

TROJAN-UNIT 1

3/4 1-23




Figure 3.1-1

Rod Bank Insertion Limits Versus Thermal Power
Four Loop Operation