

JUL 1 1980

Docket No. 50-341

Detroit Edison Company
ATTN: Mr. Edward Hines, Assistant
Vice President and Manager
Quality Assurance
2000 Second Avenue
Detroit, MI 48226

Gentlemen:

Thank you for your final report dated June 13, 1980, pursuant to 10 CFR 50.55(e) regarding defective Westinghouse Switches. We will review your final report on this matter upon receipt.

Your cooperation with us is appreciated.

Sincerely,

G. Fiorelli, Chief
Reactor Construction and
Engineering Support Branch

cc w/ltr dtd 6/13/80:
Central Files
Reproduction Unti NRC 20b
PDR
NSIC

RIII
RB
Barrett/jp
6/30/80

RIII
HW
Knop

RIII
g
Fiorelli

8007170 498

horelli

Detroit Edison

2000 Second Avenue
Detroit, Michigan 48226
(313) 237-8000

June 13, 1980
EF2-49,015

Mr. James C. Keppler
Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: 10CFR50.55(e) Item on Defective Westinghouse Switches.

Dear Mr. Keppler:

This letter is submitted as Detroit Edison's final report on the 10CFR50.55(e) item on defective Westinghouse Switches.

On December 7, 1979, Detroit Edison's Mr. H.A. Walker telephoned Mr. F.J. Jablonski of NRC Region III to report on defective Westinghouse Switches in distribution cabinets used to distribute power for plant instrumentation and control at the Fermi 2 Site. These switches were manufactured by Westinghouse Electric Corporation and furnished to Detroit Edison by the Harlo Corporation.

Edison Engineering has completed their evaluation of this deficiency. The attached report includes a description of the deficiency, and the corrective action taken. Corrective action will be completed in accordance with the construction schedule.

If you have any questions regarding this matter, please contact Mr. H.A. Walker, Supervisor - Construction Quality Assurance.

Sincerely,
W.J. Fahrner

W.J. Fahrner, Manager
Enrico Fermi 2

WJF/HAW/pn

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Division of Reactor Inspection Programs
U.S. Nuclear Regulatory Commission
Washington D.C. 20555

Mr. Bruce Little, Resident Inspector
Office of Inspection and Enforcement
Enrico Fermi 2 Construction Site
Newport, Michigan 48166

JUN 25 1980

8006270330
DUP