

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION V

1990 N. CALIFORNIA BOULEVARD SUITE 202, WALNUT CREEK PLAZA WALNUT CREEK, CALIFORNIA 94596

MAY 23 1980

Docket No. 50-508, 50-509

Washington Public Power Supply System P. O. Box 968 Richland, Washington 99352

Attention: Mr. N. O. Strand

Managing Director

Gentlemen:

Subject: NRC Inspection of WNP-3 and WNP-5

This refers to the inspection conducted by Mr. G. P. Yuhas of this office on May 13-15, 1980 of activities authorized by NRC Construction Permit Nos. CPPR-154 and CPPR-155, and to the discussion of our findings held by Mr. Yuhas with Mr. C. E. Love and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

No items of noncompliance with NRC requirements were identified within the scope of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office, within 20 days of the date of this letter, requesting that such information be withheld from public disclosure. The application must include a full statement of the reasons why it is claimed that the information is proprietary. The application should be prepared so that any proprietary information identified is contained in an enclosure to the application, since the application without the enclosure will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.



Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely,

A. E. Book H. E. Book, Chief

Fuel Facility and Materials

Safety Branch

Enclosure: IE Inspection Report Nos. 50-508/80-05

50-509/80-05

cc w/o enclosure:

M. E. Witherspoon, WPPSS

W. J. Talbott, Division Manager, WPPSS