CONNECTICUT YANKEE ATOMIC POWER COMPANY

BERLIN, CONNECTICUT
P. O. BOX 270 HARTFORD, CONNECTICUT 06101

TELEPHONE 203-666-6911

June 23, 1980

Docket No. 50-213 A01006

Mr. Boyce H. Grier, Director Region I Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

Reference: (1) B. H. Grier letter to All Operating Nuclear Power Plants, dated May 6, 1980.

Gentlemen:

Haddam Neck Plant Response to I&E Bulletin No. 80-10

This letter responds to I&E Bulletin No. 80-10, concerning potential contamination of nonradioactive systems and resulting potential for unmonitored, uncontrolled releases of radioactivity to the environment. The actions taken as required by Bulletin Items 1 and 2 are as follows:

Item 1

The plant design and operation have been reviewed to identify systems considered nonradioactive, but could possibly become radioactive through system interfaces.

Item 2

Engineering reviews have concluded that there exists a routine sampling/analysis or monitoring program for each of the systems identified in Item 1, to promptly identify any contaminating events which could lead to unmonitored, uncontrolled liquid or gaseous releases to the environment.

The specifics of these actions are available at the site for future NRC review during onsite inspection efforts. Should you have any questions, please contact us.

Very truly yours,

CONNECTICUT YANKEE ATOMIC POWER COMPANY

W. G. Counsil

Senior Vice President