



JAMES C. MOSS
PRESIDENT

TULSA GAMMA RAY, INC.

1127 SOUTH LEWIS
TULSA, OKLAHOMA 74104
585-3228

NRC License #35-17178-01

QUALITY ASSURANCE PROGRAM

1. ORGANIZATION

The final responsibility for the QA Program for Part 71 requirements rests with Tulsa Gamma Ray, Inc.

Design and fabrication shall not be conducted under this QA Program. The QA Program is implemented as shown on the attached organization chart.

The Radiation Safety Officer is responsible for overall administration of the program, training and certification, document control and auditing.

The Radiographers are responsible for handling, storing, shipping, inspection, test and operating status and record keeping.

2. QUALITY ASSURANCE PROGRAM

The management of Tulsa Gamma Ray, Inc., establishes and implements this QA Program. Training, prior to engagement, for all QA functions is required according to written procedures. QA Program revisions will be made according to written procedures with management approval. The QA Program will ensure that all defined QA Procedures, engineering procedures and specific provisions of the package design approval are satisfied. The QA Program will emphasize control of the characteristics of the package which are critical to safety.

The Radiation Safety Officer shall assure that all radioactive material shipping packages are designed and manufactured under a QA program approved by Nuclear Regulatory Commission for all packages designed or fabricated after January 1, 1979. This requirement can be satisfied by receiving a certification to this effect from the manufacturer.

3. DOCUMENT CONTROL

All documents related to a specific shipping package will be controlled through the use of written procedures. All document changes will be performed according to written procedures approved by management.

8007210205

16781

The Radiation Safety Officer shall ensure that all QA functions are conducted in accordance with the latest applicable changes to these documents.

4. HANDLING, STORAGE AND SHIPPING

Written safety procedures concerning the handling, storage and shipping of packages for certain special form radioactive material will be followed. Shipments will not be made unless all tests, certifications, acceptances and final inspections have been completed. Work instructions will be provided for handling, storage and shipping operations.

Radiography personnel shall perform the critical handling, storage and shipping operations.

5. INSPECTION, TEST AND OPERATING STATUS

Inspection, test and operating status of packages for certain special form radioactive material will be indicated and controlled by written procedures. Status will be indicated by tag, label, marking or log entry. Status of nonconforming parts or packages will be positively maintained by written procedures.

Radiography personnel shall perform the regulatory required inspections and test in accordance with written procedures. The Radiation Safety Officer shall ensure that these functions are performed.

6. QUALITY ASSURANCE RECORDS

Records of package approvals (including references and drawings), procurement, inspections, tests, operating logs, audit results, personnel training and qualifications and records of shipments will be maintained. Descriptions of equipment and written procedures will also be maintained.


- a) The records will be maintained in accordance with a written procedure.
- b) The records will be identified and retrievable.
- c) The Radiation Safety Officer will maintain a list of the records and their storage location.

7. AUDITS

Established schedule of audits of the QA Program will be performed using written check lists. Results of audits will be maintained and reported to managements. Audit reports will be evaluated and deficient areas corrected. The audits will be dependent of the safety significance of the activity being audited, but each activity will be audited at least once a year. Audit reports will be maintained as part of the quality assurance records. Members of the audit team shall have no responsibility in the activity being audited


Kendrick L. Stewart, Radiation Safety Officer
Tulsa Gamma Ray, Inc.

ORGANIZATIONAL CHART



Quality Assurance Program

ATTACHMENT 1