



Metropolitan Edison Company
Post Office Box 480
Middletown, Pennsylvania 17057
717 944-4041

Writer's Direct Dial Number

July 16, 1980
TLL 339

Office of Inspection and Enforcement
Attn: E. J. Brunner, Chief
Reactor Operations and Nuclear Support Branch
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit I (TMI-1)
Operating License No. DPR-50
Docket No. 50-289
Inspection Report 50-289/80-05

This letter is in response to Inspection Report 50-289/80-05 which contains one apparent deviation. Attached please find our response.

Sincerely,

Signed J. G. Herbein

J. G. Herbein
Vice President
TMI-I

JGH:DGM:hah

Attachment

cc: B. H. Grier
R. W. Reid
E. J. Snyder
D. DiIanni
H. Silver
J. T. Collins

A001
S
//

80072103981

INSPECTION REPORT 50-289/80-05

Deviation:

The RRR is a three volume document that had been submitted by the licensee to NRC-NRR describing the control and requirements to be imposed on Unit I restart activities. The inspectors noted that in a number of instances this document imposes requirements in addition to those found in the QA Program and implementing procedures such as GP-1008.

The inspector identified that those additional RRR requirements were not included or referenced in any implementing instructions/procedures, including engineering tasks assigned to the licensee's architect/engineer (three specific examples are discussed in paragraphs 4.c and 5.b of this report).

The failure to incorporate those additional requirements into implementing instructions/procedures is considered to be a deviation since the RRR is a written commitment to the NRC (289/50-05-01).

Response:

The failure to incorporate the additional RRR requirements into implementing instructions has been corrected by the issuance of the GAI/GPUNC TMI Project Management Manual rev. 0 dated 4/30/80 and GPUNC ES-009 rev. 0 dated 7/8/80. Paragraph 2:05 of TMI PMM directs the project engineer to ensure that all GAI work is done in accordance with RRR. GPUNC ensures same by using the Verification Checklist in ES-009.