

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
230 PEACHTREE STREET, N. W. SUITE 818
ATLANTA, GEORGIA 30303

In Reply Refer To:
IE:II:TNE
50-269, 50-270
50-287/75-1

Duke Power Company
ATTN: Mr. A. C. Thies, Senior Vice
President, Production and
Transmission
Power Building
422 South Church Street
Charlotte, North Carolina 28242

Gentlemen:

This refers to the inspection conducted by Messrs. T. N. Epps, H. L. Whitener and G. R. Jenkins of this office on January 27-31 and February 4-7, 1975, of activities authorized by NRC Operating License Nos. DPR-38, DPR-47 and DPR-55 for the Oconee-1, 2 and 3 facilities, and to the discussion of our findings held by Messrs. Epps, Whitener and Jenkins with Messrs. J. E. Smith and J. W. Hampton and other members of the Oconee staff at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

The results of our followup of previously identified matters are contained in the enclosed report as follows:

- a. The results of our inspection of your corrective action on previously identified items of noncompliance are discussed in Section II of the summary of the enclosed report.
- b. The status of unresolved items identified in previous inspection reports is discussed in Section IV of the summary of the enclosed report.



4911270817

During the inspection, it was found that certain activities under your license appear to be in noncompliance with NRC requirements. The non-compliance and references to pertinent requirements are listed in Section I of the summary of the enclosed report.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within 20 days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective steps which have been taken by you, and the results achieved; (2) corrective steps which will be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. No additional response is requested to noncompliance items I.A.4 and I.B.2.

During the inspection it was determined that a previous commitment made in writing to the Commission had not been met. The item is identified as a "deviation" and appears in Section V of the summary of the enclosed report. You are requested to inform us of your plans for implementation of this commitment.

Other infractions and deficiencies which were identified through your internal audit program are shown in the details of the attached report. In each case appropriate reports were made and corrective action was initiated or completed and no additional information is needed for these items at this time.


In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office requesting that such information be withheld from public disclosure. If no proprietary information is identified, a written statement to that effect should be submitted. If an application is submitted, it must fully identify the bases for which information is claimed to be proprietary. The application should be prepared so that information sought to be withheld is incorporated in a separate paper and referenced in the application since the application will be placed in the Public Document Room. Your application, or written statement, should be submitted to us within 20 days. If we are not contacted as specified, the enclosed report and this letter may then be placed in the Public Document Room.

Duke Power Company

-3-

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Very truly yours,



Norman C. Moseley
Director

Enclosure:

IE Inspection Report Nos.

50-269, 50-270 and 50-287/75-1

cc w/encl: J. E. Smith, Manager
Post Office Box 1175
Seneca, South Carolina 29678