

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

IE FILE COPY



Docket No. 50-346

16 1977

Toledo Edison Company
ATTN: Mr. James S. Grant
Vice President - Energy
Supply
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

46

CRESWELL
TAMBLING
INSPECTION REPORT (3)

Gentlemen:

This refers to the inspection conducted by Mr. T. N. Tambling of this office on November 16-18, 30; and December 1-2, 1977, of activities at Davis-Besse Nuclear Power Station, Unit 1, authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. T. Murray, Plant Superintendent, and members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

Certain other activities, set forth in the enclosed Appendix A to this letter, appear to be a deviation from commitments which you have made in previous correspondence with the Commission. Please advise us in writing within twenty days of the corrective action you have taken or plan to take, showing the estimated date of completion with regard to this deviation.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room, except as follows. If the enclosures contain information

8001160697

Q

DEC 16 1977

that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Gaston Fiorelli, Chief
Reactor Operations and
Nuclear Support Branch

Enclosures:

1. Appendix A, Notice of Deviation
2. IE Inspection Report No. 50-346/77-34

cc w/encls:

- Central Files
- Reproduction Unit NRC 20b
- PDR
- Local PDR
- NSIC
- TIC
- U. Young Park, Power Siting Commission

OFFICE >	RIII <i>REC</i>	RIII	RIII		
SURNAME >	Tambling/ <i>fb</i>	Knop <i>REC</i>	Fiorelli <i>GF</i>		
DATE >	12/15/77				