

TOLEDO  
EDISON

June 23, 1978

L78-278  
FILE: RR 2 (NP-32-78-07)

Docket No. 50-346  
License No. NFF-3

Crawswell

Mr. James G. Keppler  
Regional Director, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 78-061  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: June 12, 1978

Enclosed find three copies of Licensee Event Report 78-061 with a supplemental information sheet, which is being submitted in accordance with Technical Specification 6.9 to provide 14 day written notification of the subject occurrence.

Yours truly,

*Terry D. Murray*  
Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/JRL/ljk

Enclosures

cc: Dr. Ernst Volgenau, Director  
Office of Inspection and Enforcement  
Encl: 40 copies LER 78-061

Mr. William G. McDonald, Director  
Office of Management Information  
and Program Control  
Encl: 3 copies LER 78-061  
2 copies telecopied report

bcc: J.H. Barker  
P. P. Anas  
R. E. Lapp  
W. E. Nyer  
C. M. Rice  
J. C. Buck  
T. P. Beeler  
Edison Electric Institute  
Training Department  
CNRB Members

EXHIBIT 1  
page 1 of 3